

(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)	(14)	(15)	(16)	(17)
St. Croix River Area - Continued.																
2882	John Adice	St 120	Rg	36	6	36	39	174	Gravel	Unconfined	23	1947	J, S	D, S	20	11
															Supplies water for 2 farms; see table 2 for log.	
2891	Lloyd Parker	St 90	Dg	10.0	..	10	..	..	Sand and gravel	do.	8.3	July 7, 1948	J	D	..	..
2901	George Peckley	Fp 70	Dn	25	12	25	..	..	Sand (?)	do.	..	..	P	D	..	..
2911	John DiGiovanni	Fp 75	Dn	12	12	12	..	..	Gravel	Unconfined	6+	..	P, 3	D, S	60	10
2911A	Arthur Ginger	Fp 90	Dg	18	..	18	..	..	Sand and gravel	do.	12+	..	P, 12	PS	165	11
2920	Ralph Visser	Fp 60	Dn	15	12	16	..	..	do.	34+	..	..	P, 4	D, S	..	..
2922	Conrad Pruynooches	Fp 80	Dn	..	..	..	..	..	Gravel and sand	do.	..	..	P	..	95	14
2925	C. S. Lake Canning Company	Fp 85	Dg	150	16	50	13	37	Gravel	do.	11	When drilled	C, 450	Ind	..	..
2932	Henry Zellers	Fp 85	Dn	26	12	23	..	..	do.	do.	12+	..	C, 5	D, S	125	8
															Water reported to contain iron.	
2943	Patricia Brown	Fp 80	Dn	15	12	15	..	..	Sand and gravel	do.	11+	..	P, 16	D	115	8
															do.	
2951	Henry Edmunds	Fp 85	Dn	12	12	12	..	..	Gravel	do.	10+	..	P, 3	D	..	..
															do.	
2961	L. G. Pike	Fp 85	Dg	15	12	12	..	..	do.	do.	4+	..	P, 4	D	..	..
															do.	
2962	Geo. Gervais	Fp 85	Dg	14	12	12	..	..	do.	do.	9+	..	J, 6	D, S	..	..
															do.	
2964	J. R. Berg	Fp 90	Dg	12.5	..	12.5	..	..	Sand	do.	8.4	June 30, 1948	P, 3	D	115	6
															Water reported to contain trace of iron.	
2964L	Sam Sorenson	St 120	Dg	12	..	..	..	..	Gravel, coarse	do.	..	..	P, 5	D, Ind 220	..	10
															Supplies 2 homes and small sawmill; temperature of water 52° F.	
2965	Everson Hardwood Lumber Co.	St 120	Dr	101	6	100	100	1	Gravel	Confined	3.0	July 1, 1948	J, 30	N	30	1134
															Flowed when first drilled; penetrated "hardpan" to 12 feet and clay for 88 feet above aquifer; temperature of water 49° F.	